



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2021 DEERE 317G

Model: 2021 DEERE 317G

Machine Hours: 1,335

Condition: Good

Specifications:

- EROPS with Heat & Air Conditioning, Radio
- SJC Controls
- Auxiliary Hydraulics
- Rear Camera
- 61 HP Yanmar Diesel Engine
- 72" General Purpose Bucket
- Hydraulic SSL Quick Attach
- 16" Rubber Tracks
- 2,125 lbs Lift Capacity, 8,195 lbs Operating Weight



Engine and Performance

- Engine Operation: Smooth start-up with no unusual noises or vibrations.
- Exhaust System: Emission levels within normal limits; no visible smoke.
- Oil Levels and Quality: Oil is at the recommended level with no contamination.
- Cooling System: Radiator and coolant reservoir inspected—no leaks or damage.
- Air Filter: Clean and free from blockages; replaced if necessary.

Hydraulic System

- Hydraulic Fluid Levels: Proper level, clean fluid, and no signs of leaks.
- Hoses and Connections: Inspected for cracks, wear, and leaks; no issues found.
- Auxiliary Hydraulics: Tested for functionality; operates smoothly under load.

Loader Mechanism

- Loader Arms: Inspected for structural integrity; no signs of cracks or excessive wear.

- Pins and Bushings: Checked for wear; adequately lubricated.
- Hydraulic Cylinders: No leaks or damage; operates smoothly.

Operator Cabin

- Climate Control: Heat and air conditioning tested; fully functional.
- Radio and Electricals: Operational with no defects.
- Instrumentation Panel: All gauges and indicators functioning as expected.
- Controls (SJC): Responsive and free of defects; smooth operation.
- Seat and Safety Restraints: Inspected for wear and functionality; no issues.

Undercarriage and Tracks

- Rubber Tracks: 16" tracks exhibit uniform wear with approximately 85% tread remaining.
- Track Tension: Adjusted to manufacturer specifications.
- Rollers and Idlers: Checked for wear and proper alignment.

Bucket and Attachments

- 72" GP Bucket: No dents, cracks, or excessive wear; cutting edge in good condition.
- Hydraulic SSL Quick Attach: Operates smoothly, securely locks attachments.

Electrical System

- Lighting: All exterior and interior lights operational, including rear camera.
- Battery and Wiring: Battery tested and connections inspected; no corrosion or damage.

Safety and General Inspection

- Backup Camera: Tested and functioning; clear visibility.
- Safety Alarms: Operational with no defects.
- Fire Extinguisher: Present and within certification (if applicable).

Inspection Summary

The 2021 DEERE 317G Skidsteer is in good condition, with all systems functioning as intended. Minor wear consistent with 1,335 hours of use, but no significant defects detected. The machine is work-ready and fully operational, meeting performance expectations for its class and specifications.