



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2021 DEERE 318G

Equipment Details:

- Make/Model: 2021 DEERE 318G
- Operating Hours: 122
- Condition: Good Condition



Inspection Checklist:

Structural Components

- Loader Arms: Inspected for bends, cracks, and excessive wear. Result: No issues found; loader arms in excellent structural condition.
- Chassis and Frame: Examined for integrity and alignment. Result: Solid frame, no damage, cracks, or welding observed.

Hydraulic System

- Hydraulic Hoses and Connections: Checked for leaks, wear, or damage. Result: Hoses and connections are secure with no leaks detected.
- Hydraulic Fluid Level: Verified against manufacturer's specifications. Result: Fluid level within range; no contamination or discoloration.
- Auxiliary Hydraulics: Tested for functionality and pressure. Result: Fully operational, no issues noted.

Powertrain

- Engine Performance: Inspected for smooth operation, unusual noises, and vibrations. Result: Engine runs smoothly; no unusual noises or vibrations.
- Engine Compartment: Checked for cleanliness, leaks, and overall condition. Result: Clean compartment; no visible leaks or loose components.

- Transmission and Drive Components: Tested for responsiveness and wear. Result: Drive components in good working condition.

Tires

- Condition and Tread: Inspected for uniform wear and damage. Result: Tires show uniform wear with at least 90% tread remaining.

- Tire Pressure: Verified pressure within manufacturer's recommended range. Result: All tires properly inflated.

Operator Station

- Controls and Switches: Tested for responsiveness and functionality. Result: All controls are responsive and free of defects.

- Seat and Restraints: Checked for wear and operability. Result: Seat in good condition; restraints functional.

- Visibility: Confirmed clear visibility from operator station. Result: Operator station provides unobstructed view.

Electrical System

- Battery and Connections: Inspected for secure connections and performance. Result: Battery connections secure; no corrosion present.

- Lights and Indicators: Tested for proper operation. Result: All lights and indicators functional.

Bucket and Attachments

- Hydraulic Quick Attach System: Inspected for secure locking and functionality. Result: Fully operational; no defects found.

- Bucket Condition: Examined for wear, dents, and cracks. Result: Bucket in excellent condition, minimal wear.

General Appearance

- Exterior Panels: Inspected for dents, scratches, and overall appearance. Result: Panels in good condition; minor cosmetic wear consistent with use.

- Paint and Decals: Checked for peeling, fading, or damage. Result: Paint and decals in good condition.

Inspection Summary:

The 2021 DEERE 318G Skidsteer has been thoroughly inspected and is in Good Condition. With only 122 operating hours, the machine shows minimal wear and operates smoothly. All major systems, including the hydraulic system, powertrain, and electrical components, are functioning as intended. Structural integrity is excellent, and the tires exhibit significant

remaining tread life. This Skidsteer is work-ready and requires no immediate repairs or maintenance.

Inspector's Notes:

This Skidsteer has been maintained well and is a reliable choice for various applications. The low hours and operational condition make it a valuable asset for prospective buyers.