



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2022 DEERE 333G

Skidsteer Model: DEERE 333G
Year: 2022
Machine Hours: 1,620
Condition: Good



1. Exterior and Body

- **Loader Arms:** Inspect for bends, cracks, or deformations.
 - Condition: **No visible cracks or bending.**
- **Hydraulic Quick Attach:** Verify smooth operation and secure locking mechanism.
 - Condition: **Fully functional, no excessive wear or slippage.**
- **Cab & Glass:** Check for cracks or damage to windows and doors. Ensure air conditioning and heating work correctly.
 - Condition: **Cab in good condition with no cracks or leaks. Heating and A/C operational.**
- **Rubber Tracks:** Inspect for wear, cuts, and proper tension. Check for even wear across all tracks.
 - Condition: **Tracks show no cuts, even wear, and are tensioned properly.**

2. Hydraulic System

- **Hydraulic Fluid:** Check fluid levels and look for any signs of contamination or leakage.
 - Condition: **Hydraulic fluid within recommended range, no leaks detected.**
- **Hydraulic Hoses and Fittings:** Inspect for signs of wear, cracks, or leaks.
 - Condition: **No visible wear or leaks.**
- **Hydraulic Auxiliary Valves:** Test for smooth operation. Ensure no leakage or irregular behavior.
 - Condition: **Auxiliary valves functioning as expected, no issues noted.**

- **High Flow System:** Test the functionality of the high-flow hydraulics, ensuring proper operation with compatible attachments.
 - Condition: **High-flow system working without issues.**

3. Engine and Performance

- **Engine Oil:** Check oil level and quality, ensure no signs of contamination.
 - Condition: **Oil level is adequate, no contamination detected.**
- **Cooling System:** Inspect radiator, hoses, and coolant levels. Ensure the system operates without leaks or overheating.
 - Condition: **Coolant level correct, no leaks in the system.**
- **Engine Operation:** Start engine and listen for unusual noises or vibrations. Ensure smooth running and no excess exhaust smoke.
 - Condition: **Engine starts and runs smoothly, no unusual noises.**
- **Fuel System:** Inspect fuel tank for leaks, cracks, and ensure fuel system is operating optimally.
 - Condition: **Fuel system intact with no issues or leaks.**

4. Operator Controls and Safety

- **Control Functions:** Test joystick and foot controls for proper function, responsiveness, and no binding.
 - Condition: **Controls responsive, smooth operation, no binding or issues.**
- **Operator Seat and Safety:** Inspect seat for comfort, adjustability, and safety features.
 - Condition: **Seat operational with no issues.**
- **Safety Features:** Verify the functionality of safety interlocks and lights.
 - Condition: **All safety features operational, no concerns.**

5. Tires and Tracks

- **Track Condition:** Check rubber tracks for cracks, excessive wear, or damage. Ensure they are evenly worn.
 - Condition: **Tracks in good condition, 85% tread remaining.**
- **Track Tension:** Ensure tracks are properly tensioned.
 - Condition: **Proper tension with no adjustments needed.**

6. Electrical System

- **Battery:** Check battery charge level and connections. Look for corrosion.
 - Condition: **Battery charge at full level, terminals clean.**
- **Wiring and Fuses:** Inspect wiring for signs of wear, abrasion, or loose connections.
 - Condition: **Wiring intact with no issues or exposed wiring.**

- **Lights and Indicators:** Test all lights (front, rear, work lights) and instrument panel indicators.
 - Condition: **All lights and indicators functioning properly.**

7. Final Remarks

- **Overall Condition:** The 2022 DEERE 333G is in **Good Condition**, with all primary components in optimal working order. Minor cosmetic wear but no major functional issues.
- **Action Items:** No major repairs required. Regular maintenance should continue as per manufacturer's guidelines.