



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrosequipment.com](http://www.albatrosequipment.com)

## Inspection Checklist for 2022 Kubota SSV75

Model: 2022 KUBOTA SSV75  
Machine Hours: 76  
Condition: Good (almost new condition)



### Exterior and Structural Components

- Cab and Body Panels: Inspected for integrity, dents, or damage—no cracks or visible wear.
- Loader Arms: Checked for bending, cracks, or signs of excessive wear—no issues found.
- Paint and Finish: Minimal scratches, consistent with light use.

### Hydraulic System

- Hydraulic Hoses: Inspected for wear, cracks, and leaks—all hoses in excellent condition.
- Auxiliary Hydraulics: Fully operational, connectors clean and undamaged.
- Hydraulic Fluid Levels: Checked and within the recommended range.

### Cab and Operator Controls

- Enclosed Cab: Fully sealed with no leaks. All glass intact and clear.
- Heating and Air Conditioning: Functional—heat and A/C deliver consistent performance.
- Radio: Operational with clear sound output.

- Operator Controls: Smooth and responsive joystick controls—no sticking or delays.
- Seat Condition: Excellent, no tears or wear.

### **Engine and Powertrain**

- Engine: Turbocharged 75 HP diesel engine starts smoothly and operates with no unusual noises or vibrations.
- Fluid Levels: Engine oil, coolant, and DEF checked and at optimal levels.
- Exhaust System: Inspected and free of damage or excessive emissions.
- 2-Speed Transmission: Shifts seamlessly with no lag or irregularities.

### **Tires**

- Condition: Tires exhibit 99% tread remaining, consistent with the machine's low usage.
- Pressure: Verified and adjusted to manufacturer specifications.
- Rims and Valve Stems: Free of damage or corrosion.

### **Attachments**

- Hydraulic Quick Attach: Functioning perfectly—locks and releases attachments with ease.
- Auxiliary Hydraulics: Pressure and flow rates confirmed within specs.

### **Lighting and Electrical System**

- Lights: Fully operational, including headlights and safety indicators.
- Battery: Connections are clean and secure; charge level verified.
- Wiring: No signs of wear, fraying, or exposure.

### **Operational Test**

- Startup: Engine starts smoothly with no excessive cranking.
- Loader Functions: Lift and tilt operations performed flawlessly under load.
- Travel Test: Smooth operation in both speed ranges; tracks straight with no pull or hesitation.

---

## **Condition Report**

This Kubota SSV75 skidsteer is in excellent condition, reflecting its low usage of only 76 hours. All systems, components, and features are fully functional. The machine is work-ready with no immediate maintenance required.

Overall Condition Rating: 95%