



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2022 DEERE 332G

Equipment Details

- Model: 2022 DEERE 332G
- Hours: 262
- Condition: Good
- Features:
 - 100 HP Diesel Turbo Engine
 - 2-Speed Transmission
 - Switchable Controls
 - Keyless Start
 - Rearview Camera
 - Excellent Tires
 - 84" Bucket
 - Bucket Hinge Pin Max Height: 11 ft
 - Bucket Breakout Force: 9,250 lb
 - Tipping Load: 7,200 lb



Engine and Powertrain

- Engine operates smoothly with no unusual noises, smoke, or vibrations. Turbocharger functioning optimally.
- Oil Levels: Checked and within manufacturer specifications. No signs of contamination or leaks.
- Coolant Levels: Inspected and at proper level; no leaks detected.
- Battery and Electrical Systems: Voltage and charging system inspected; battery terminals clean and connections secure.

Hydraulic System

- Hydraulic Fluid Levels: Fluid within optimal range, clean, and free from contamination.
- Hydraulic Hoses: Inspected for wear, cracks, or leaks—no issues found.
- Auxiliary Hydraulics: Operates correctly with no signs of reduced flow or pressure loss.

Loader Arms and Bucket

- Loader Arms: Structurally sound with no cracks, bends, or signs of excessive wear.
- Bucket Condition: 84" bucket inspected; cutting edge and sides show minimal wear.
- Bucket Hinge Pins: Secure and lubricated; max height verified at 11 ft.

Transmission and Drive System

- 2-Speed Transmission: Engages smoothly with no abnormal noises or delays.
- Drive Motors and Final Drives: Inspected and in good condition; no signs of leaks or overheating.

Tires

- Tire Condition: Excellent condition with uniform wear and ample tread remaining (>90%).
- Tire Pressure: Confirmed within manufacturer-recommended range.

Operator Cabin and Controls

- Cab Interior: Clean and well-maintained. Seat, switches, and joystick controls are in excellent condition.
- Switchable Controls: Fully functional, allowing operator to switch between control styles seamlessly.
- Rearview Camera: Provides a clear, unobstructed view; no malfunctions noted.
- Keyless Start System: Operational and secure.

Lighting and Visibility

- Lights and Indicators: All lights, including work lights and indicators, are operational.
- Windows: Clean, with no cracks or damage.

Chassis and Structure

- Frame and Chassis: Inspected for cracks, corrosion, or other damage—none found.
- Paint and Finish: Good condition, with minor cosmetic wear from normal use.

Summary

The **2022 DEERE 332G** Skidsteer has been thoroughly inspected and is confirmed to be in **Good Condition** with no significant defects or operational issues. Minor cosmetic wear is consistent with the machine's 262 hours of usage. This Skidsteer is ready for work and meets all manufacturer specifications for performance and safety.