



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2023 BOBCAT T62



Exterior Condition

- **Body Panels:** Panels are in good condition with no significant dents or damage. Paint is intact with minimal wear, consistent with light use.
- **Loader Arms:** Inspected for cracks, bends, and excessive wear — no issues detected. Pins and bushings show minimal wear, securely fastened and operating smoothly.
- **Hydraulic Connections:** All hoses and connections inspected for leaks or visible damage — no leaks found.

Hydraulic System

- **Hydraulic Fluid Levels:** Fluid levels are within the manufacturer's recommended range. No contaminants or discoloration observed in hydraulic fluid.
- **Auxiliary Hydraulics:** Inspected for proper function and pressure — all operational.

Engine

- **Startup and Operation:** Engine starts smoothly with no unusual noises or vibrations. No excessive exhaust smoke observed during operation.
- **Fluid Levels:** Oil, coolant, and other fluids are at appropriate levels and show no contamination.
- **Belts and Hoses:** All belts and hoses are in good condition, free from cracks or fraying.

Operator's Cabin

- **Interior Condition:** Cabin is clean and free of damage or excessive wear. Seat and controls are in excellent condition.

- **Climate Control (Heat and A/C):** Heater and air conditioning tested — both functioning effectively.
- **SJC Controls:** Joystick controls are responsive and operate smoothly.

Undercarriage

- **Tracks:** Rubber tracks exhibit uniform wear with over 95% tread life remaining. No visible cracks, tears, or separations in the tracks.
- **Rollers and Idlers:** Inspected for wear and alignment — all components in good condition.

Performance and Safety Features

- **Hydraulic Performance:** Loader arms and auxiliary hydraulics tested under load — all operating efficiently.
- **Safety Features:** All safety systems and switches operational. Backup alarm and lights tested — fully functional.

Electrical System

- **Battery and Connections:** Battery terminals inspected for corrosion — no issues found. Battery holds a full charge and operates as expected.
- **Lighting:** Front and rear work lights tested — all operational.

Attachments

- **Bucket:** General-purpose bucket inspected for wear and structural integrity — no damage or cracks. Quick-attach mechanism operates smoothly and locks securely.

Summary

The 2023 BOBCAT T62 is in good condition with minimal hours (52). All systems, including the engine, hydraulics, climate control, and safety features, have been inspected and found to be fully operational. Tracks show over 95% tread life, and the loader arms and auxiliary hydraulics are in excellent working order. This machine is ready for immediate work with no necessary repairs or maintenance at the time of inspection.

Inspector's Note: This Skidsteer is a well-maintained unit, ideal for buyers seeking a reliable machine with modern features like cab heat, A/C, and SJC controls.