



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2023 DEERE 333G

Model: 2023 DEERE 333G
Machine Hours: 468 Original Hours
Condition: Good



General Overview

- **Machine Details:** 2023 DEERE 333G, High Flow, 2-Speed with Creeper Gear, ISO Switch Controls, Rear View Camera, Warranty valid until October 16, 2026.
- **Visual Inspection:** Exterior components are clean, free from excessive wear, dents, or corrosion. No significant structural damage or modifications.

Engine and Powertrain

- **Engine Performance:** Engine runs smoothly with no unusual noises or vibrations.
- **Exhaust System:** Inspected for leaks and blockages—no issues detected.
- **Cooling System:** Radiator and hoses in good condition with no leaks or obstructions.
- **Fluid Levels:** Engine oil, coolant, and other essential fluids are within manufacturer-recommended ranges.

Hydraulic System

- **Hydraulic Lines and Hoses:** Checked for wear, cracks, and leaks. All hoses are in excellent condition.

- **Hydraulic Fluid:** Levels are correct, and fluid is clean with no signs of contamination.
 - **Cylinders:** Inspected for proper function and leaks. No issues detected.
 - **High Flow Performance:** Tested for efficient operation under load—system performs as intended.
-

Tracks and Undercarriage

- **Tracks:** Caterpillar tracks show uniform wear with approximately 85% tread remaining.
 - **Rollers and Idlers:** Free of damage and excessive wear; all components rotate smoothly.
 - **Track Tension:** Adjusted to manufacturer specifications and within operational limits.
-

Operator Controls and Cab

- **Operator Controls:** ISO switch controls are responsive and free of defects.
 - **Display Panel:** Fully operational with clear indicators and no error codes.
 - **Air Ride Seat:** Cloth seat with heating is in excellent condition and functions properly.
 - **Camera and Visibility:** Rearview camera is clear, functional, and provides a wide field of view.
 - **Cab Environment:** HVAC system (heat and air conditioning) operates correctly. No visible signs of leaks or blockages.
-

Loader Arm and Quick Attach

- **Loader Arm:** Inspected for structural integrity; no cracks, bends, or excessive wear.
 - **Self-Leveling and Ride Control:** Tested; performs efficiently under all operational scenarios.
 - **Quick Attach System:** Functions smoothly and securely attaches/detaches buckets and other attachments.
-

Electrical System

- **Battery and Cables:** Battery is fully charged, and terminals are free of corrosion.
 - **Lighting:** All external and internal lights operate correctly.
 - **Wiring Harness:** Inspected for wear and secure connections; no issues detected.
-

Other Components

- **Louver Rear Grill:** Securely installed and free from damage.
 - **Severe Duty Door:** Inspected for structural integrity and smooth operation.
 - **Pre-Cleaner:** Air intake system is clean and free of debris.
-

Overall Condition Summary

This 2023 DEERE 333G Skidsteer is in good overall condition. All critical systems have been inspected and are operational. With only 468 original hours and an extended warranty until October 16, 2026, this machine is ready for immediate use with minimal expected maintenance.